United States Environmental Protection Agency – Region 2 CERCLA Removal Action Work Order



Contractor	Kemron	Contract #	EP-S2-10-01 A23K	TO#: 0	0067	Date	February 18, 2014–February 21, 2014
EPA Region	2	Site ID			0700 – 1630 hours		
Site Name		Barrel and Drob Harris Lane	rum Site , Elk, Gloucester	County,	New Je	rsey	
OSC	Keith Glenn						
RM	Gary Beland						
Monitors	Keith Gle	nn / Margaret (Gregor				Work Order #17B

Personnel Authorized Hrs/day Otto Description Hrs/day							
Qty	Description	Hrs/day	Qty	Description	HIS/day		
- / /-					0		
1	Response Manager	9	1	Foreman	9		
1	FCA	9	0	Senior Electrical Engineer	0		
1	Chemical Technician	9	0	Senior Civil Engineer	0		
1	Operator	9	6	Clean-Up Technician	9		
1	T&D Coordinator	9	0	Hydro-Geologist	0		
2	Chemist	9	0	Structural Engineer	0		
					_		
	H						

Equipment and Expendable Materials Authorized						
Description	Qty	Description	Qty			
Truck	3	Cell Phone	2			
Van	1	Computer	2			
Portable toilets	3	Drum carts	2			
Bob Cat	1	Supplied Air				
Generator	2	Drum sampling equipment				
Light Tower	1	Dumpster	1			
Office Trailer	1	Connex (one for Decon)	2			
High Capacity Copy Machine w/ Scan Cap.	1	Printer	2			
0 1 1		Fork Lift (including Lull)	2			

Special Comments/OT Authorization, DBA Authorization & Other Specialized Instructions

-Hours listed may be used for off-site work for the FCA, Chemist, Chemical Technician, T&D Coordinator and Response Manager. Off-site work hours are authorized in the case of inclement weather causing a Site closure.

⁻Hours authorized are not to exceed 50/week/person. OT hours are authorized.

United States Environmental Protection Agency – Region 2 CERCLA Removal Action Work Order



Contractor	Kemron	Contract #	EP-S2-10-01	TO#:	0067	Date	February 18, 2014-February 21, 2014	
EPA Region	2	Site ID	A23K	Shift			0700 - 1630 hours	
Site Name	Annual Control of the	Barrel and Dr b Harris Lane	rum Site , Elk, Gloucester	County, 1	New Je	rsey		
OSC	Keith Glenn							
RM	Gary Bela	and						
Monitors	Keith Gle	nn / Margaret C	Fregor				Work Order #17	

Description of Work To Be Performed

The following is the current schedule of activities and anticipated completion dates. Any circumstances that may alter the dates further should be discussed with the OSC.

- Maintain functionality and cleanliness of a personnel decontamination area.
- Provide internet service.
- Provide potable water service for the office.
- Provide adequate supplied air for all workers.
- Provide security guards for off-hours, including weekends, holidays and Site closures due to inclement weather.
- Provide for waste management of on-site operations.
- Mange personnel during Level B operations to ensure appropriate PPE is used and Site protocols are followed to safely enter the hot zone, open containers, evaluate them, and generate appropriate documentation on finding.
- Organize and maintain the drum segregation areas, or drum fields, by hazardous class.
- Continue overpacking of containers that are leaking or deemed high-hazard.
- Continue cleaning and preparing containers for shipment.
- Prepare acid, base, flammable waste streams for transport and disposal.
- Review analytical data and generate bids for transport and disposal of materials.
- Award subcontract for disposal of hazardous materials.
- Continue the collection of composite samples for disposal purposes.
- Generate bid package(s) for the disposal of additional materials.
- Collect samples of neutral waste streams for VOC analysis and inorganic analysis.
- Conduct abbreviated HazCat operations for oxidizer waste group to determine if waste stream volume can be reduced.
- Ensure that updated drum tracking database is provided to OSC on a daily or weekly basis.

Continue to provide OSC with 1900-55's, off-site hour reports, and daily activity reports. Draft 1900-55s shall be delayed no more than 2 weeks of services.

Follow Region 2 Green policies to include recycling of paper waste. Follow recommendations outlined in Region 2 Clean and Green Policy. This includes authorization for additional electrical charges which are supplemented by alternative energy sources.

Ensure the Health and Safety of all Kemron personnel on-site.

I certify that the above work is ordered and auth the performance of the above cited Task Order.	orized in	I acknowledge receipt of this work order.	1.
Signature		Signature Saufe ASI	11
Printed Name and Title Keith Glenn, Federal On-Scene Coordinator	Date 2/17/14	Printed Name and Title Gary Beland, Kemron Response Manager	Date 02-17-14